



A-01018 FIGS. 1A-6




OBLON, SPIVAK, ET AL DOCKET #: 205379US0 INV: Sadayuki IWAI SHEET 2 OF 5









RETARKS	LAYER 10) WAS TOO THIN TO CLOSELY BOUD IT TO LAYER	-	EXTENSION AND SHIFT OF IMAGE BECAME NOTICEABLE	GOOD TRANSFIRE WAS ATTAINED EVEN TO ROUGH PAPER	CRACK WAS TO OCCUR, DEPENDING ON THE KIND OF COATING LAYER		TROUGH MAGE EXTENSION WAS NOTCEABLE, IT COULD BE COPED WITH BY INAGE PROCESSING	IMAGE EXTENSION AND DURABILITY OF SURFICE LAPER WERE CRITICAL
PURAB/UT)	×	0	0	0	◁	◁	△	×
IMAGE DURABILITY	0	0	△	◁	△	٥	×	×
1 8	1	ဇ	4	လ	ည	ഹ	ည	5
THICKNESS OF TRANSFER TO MAR LAYER IOI CRUBBER) [56600] TO	3.0	5 0	100	200	009	1000	2000	3000